



All visible surfaces have to be free of surface defects /
Sämtliche Sichtflächen müssen frei von Oberflächendefekten sein
Missing dimensions please check 3D-data, 3D-data are generally binding /
Fehlende Maße bitte den 3D-Daten entnehmen, 3D-Daten generell bindend

		general tolerance ISO 2768-mK toleration acc. to ISO 8015	edge ISO 13715	Scale: 1:1	Weight: -	
		Material: -		Part name: SE-IN-e20		
Revision		Date	Name	Drawing No.:		
Drawn		29.01.2018	hosm	Sheet 1		
Check		29.01.2018	hosm	of 1		
Rel.		29.01.2018	hosm	Size: A2		
Project No.: -		Article No.: -		Drawing No.:		
Rev.	Description	Date	Author	-		